

ASRockind Technical Reference - Q&A

Question	I find Intel Braswell platform may not boot up properly when using the customized or old versions of BIOS. How do I fix it?
Release date	2020/4/16
Product	Braswell platform: IMB-154, IMB-155, SBC-220, N3160-NUC IPC
FAQ type	<input type="checkbox"/> Specification <input type="checkbox"/> OS & Driver <input type="checkbox"/> Application <input checked="" type="checkbox"/> BIOS/FW <input type="checkbox"/> Others

Answer:

ASRock industrial has released the BIOS to update C-X & D-X Stepping CPU microcode on all Braswell Platform. The detailed BIOS versions for Microcode update are shown as below. Please check if your BIOS version is newer than these versions.

Model	BIOS Version
IMB-154	P1.60
IMB-155	P2.00
SBC-220	P1.80
N3160-NUC IPC	P1.60